Appendix A: Building Inventory and Relocation Costs

Documents Included:

- Relocation Cost Estimate
- Individual Village Site Work and Water Sewer Landfill Cost Estimates
- Transportation System Costs
- Construction Camp Cost Estimate Kivalina
- Construction Camp Cost Estimate New Sites
- Power and Fuel Cost Summary
- Buildings Cost Analysis Summary Move/Replace Buildings
- Building 45 Info Sheet
- Building 48 Info Sheet
- Building 52 Info Sheet
- Building 66 Info Sheet
- Building 74 Info Sheet
- Building 75 Info Sheet
- Building 77 Info Sheet
- Building 79 Info Sheet
- Building 80 Info Sheet
- Building 94 Info Sheet
- Building 107 Info Sheet
- Building 120 Info Sheet
- Building 122 Info Sheet
- Building 123 Info Sheet
- Building 128 Info Sheet
- Building 131 Info Sheet
- Building 143 Info Sheet
- Building 144 Info Sheet
- McQueen School Aerial Photo
- Gravel Haul Costs / Time Analysis

Sitework Cost Estimate Summary

Site	Simiq	Tatchim Isua	Imnakuk Bluffs	Kivalina	Kiniktuuraq	Igrugaivik	Kuugruak
Tasks							
Sitework ¹	\$ 167,400,000	\$ 70,400,000	\$ 165,900,000	\$ 109,600,000	\$ 163,700,000	\$ 164,800,000	\$ 164,800,000
Erosion Protection ⁵	\$ 231,000	\$ 231,000	\$ 231,000	\$ 7,151,550	\$ 2,613,600	\$ 1,045,440	\$ 2,961,750
Construction Camp ²	\$ 606,000	\$ 606,000	\$ 606,000	\$ 902,670	\$ 606,000	\$ 606,000	\$ 606,000
(over 5-year Construction Period)							
Power & Fuel	\$ 5,292,000	\$ 5,292,000	\$ 5,292,000	\$ 5,292,000	\$ 5,292,000	\$ 5,292,000	\$ 5,292,000
Move Buildings	\$ 1,125,000	\$ 1,125,000	\$ 1,125,000	\$ 1,125,000	\$ 1,125,000	\$ 1,125,000	\$ 1,125,000
New Buildings	\$ 52,690,000	\$ 52,690,000	\$ 52,690,000	\$ 52,690,000	\$ 52,690,000	\$ 52,690,000	\$ 52,690,000
Water/Sewer System & Landfill	\$ 21,119,261	\$ 21,521,638	\$ 19,844,807	\$ 19,473,814	\$ 22,125,007	\$ 20,521,057	\$ 18,146,638
Transportation System ³	\$ 3,056,000	\$ 3,056,000	\$ 3,056,000	N/A	N/A	N/A	N/A
Total Cost:	\$ 251,500,000	\$ 154,900,000	\$ 248,700,000	\$ 196,200,000	\$ 248,200,000	\$ 246,100,000	\$ 245,600,000

- 1. Sitework includes airport construction.
- 2. Construction Camp costs include mobe/demob, construction and removal.
- 3. Shuttle transportation system costs over 3-year period is proposed between villages, when two villages are operating at the same time.
- 4. Costs are in 2006 dollars
- 5. Erosion protection costs are for boat staging area erosion protection, river erosion protection, plus shoreline erosion protection.

Sitework Cost Estimate Simig

Simiq Site Estimate

	Task/Item	Quantity		Units/LF	LF of Item	Un	its	Unit Cost		Total
	Site Preparation									
1	Gravel Source Development	1				LS		\$10,000.00		\$10,000
2	Site Design Survey	1				LS		\$30,000.00		\$30,000
3	Mob/Demob	1				LS		\$130,000		\$130,000
4	Site Pad Gravel (9 ft)	1,489,890		40,227,029	9.00	CY		\$70		\$104,292,298
5	Road over Lagoon,	4,220								
6	Road to Site, Gravel (includes labor)	14,120				LF		\$450		\$6,354,000
7	Road to Runway, Gravel (includes labor)	2,560				LF		\$450		\$1,152,000
8	Road to Sewage Treatment, Gravel (includes labor)	in Runway				LF		\$450		
9	Road to Landfill, Gravel (includes labor)	8,500				LF		\$450		\$3,825,000
10	Road Bridge	60				LF		\$200		\$12,000
11	Road Culvert	1,000				LF		\$25		\$25,000
12	Hi-Density Insulation (8")	0				SY		\$45		
13	Geotextile Fabric	509,000				SY		\$10		\$5,090,000
14	Boat Staging Gravel (90 X 660 X 6)	13,200				CY		\$70		\$924,000
15	Barge Staging Gravel (208 X 208 X 5)	217,800				CY		\$70		\$15,246,000
16	Runway Gravel (6,000 lf)	221,000				CY		\$70		\$15,470,000
17	Storm Drainage Piping	14,000				LF		\$75		\$1,050,000
18	Storm Drainage Manholes	45				EA		\$3,000		\$135,000
19	Camp Security Fence	1,100				LF		\$20		\$22,000
_	Camp Raw Water Line	500				LF		\$60		\$30,000.00
21	Gravel Pad Labor/Season (Task Cost Tab)	2						\$3,040,000		\$6,080,000
	Village Construction Camp/Season	5						\$167,000		\$835,000
	Airport Runway Labor/Seas. (Task Cost Tab)	2						\$3,040,000		\$6,080,000
	Airport Construction Camp/Season	2						\$167,000		\$334,000
25	Facility Maintenance Equipment	1				LS				\$283,900
_	Total Sitework Cost									\$167,410,198
200	IA wasan Dools	1 4	1	5.0	700.0	101/		It-FO		I#47F 000
	Armor Rock	1		5.0	700.0	CY		\$50		\$175,000
	2"-8" Rip-Rap	1		2.3	700.0	CY		\$20		\$32,200
28	Erosion Fabric	1		3.4	700.0	SY		\$10	ļ	\$23,800
	Total Errosion Protection Cost									\$231,000

Assumptions

- 1 * Construction Camp Cost covers the entire construction season.
- 2 Road bridges will be precast, reinforced concrete manufactured off site and delivered
- 3 Gravel cost is delivered to site. Placement of gravel is included in Item 22 Gravel Pad Labor
- 4 Camp water line will be of different length depending on the location of the site. Length used is a guess from knowledge of site area.
- 5 All periods used for construction duration have been taken from Kivalina Master Relocation Schedule, Phase 6, dated 11/16/04
- 6 Site survey shown here is for initial design survey. Survey required during construction is included in Items 22, 24. Design survey for airport is included.
- Mob/Demob cost shown is a one-time cost associated with shipping equipment and camp to/from the site and set-up/tear-down at beginning/end of project.
- 8 Item 4 Site Pad Gravel is calculated using 2-depths; one using gravel alone and a second (Alt) using gravel over hi-density foam insulation.
- 9 Items 5, 6, 7, 8, 9 are gravel costs for material volume required to build roads to access the sites. Labor for placement is included in Items 22, 24
- 10 Items 10, 11 are guesses at the number of
- 11 Armor Rock shown in Item 26 is assumed to be minimum 4-man rock.
- 12 The 2"-8" rip-rap shown in Item 27 is fill behind Armor Rock.
- 13 Facility Maintenance Equipment item assumes contractor will leave used: backhoe/loader, road grader, small dozer, 10 YD dump truck for community use at comonstruction completion

 Grader, 1999 Cat 140HNA
 \$145,000.00

 Backhoe/Loader, 2001 Cat 416C
 \$45,000.00

 Dozer, 1998 Cat D4CIIIXL
 \$54,000.00

 Dump Truck, 1998 Ford L9501
 \$39,900.00

 \$283,900.00

Estimated Costs

Simiq

Village Kivalina Simiq

Item	Line Item		Estimated	Adjusted	Total
No.	Description	Unit	Quantity	Unit Cost	Cost
1	Household water and sewer plumbing	EA	100	\$20,267.59	\$2,026,759
2	Sewage collection mains or services (gravity or force), buried	LF		#DIV/0!	\$0
3	Sewage collection mains or services (gravity or force), above ground	LF	13,325	\$102.59	\$1,366,994
4	Sewage lift station	EA	1	\$281,226.02	\$281,226
5	Vacuum sewer plant, no foundation	SF	2,500	\$487.80	\$1,219,492
6	Septic tank, and drainfield, individual household	EA	0	#DIV/0!	\$0
7	Septic tank, community	EA	0	#DIV/0!	\$0
8	Drainfield, community	SF	0	#DIV/0!	\$0
9	Utilidors, above ground, including water and sewer, mains or services	LF	5,000	\$286.71	\$1,433,543
10	Sewage lagoon, barrow, local material	Acre	10	\$201,278.84	\$2,012,788
11	Sewage discharge works	LF	6,745	\$131.14	\$884,565
12	Water distribution, mains or services, above ground	LF	17,895	\$96.61	\$1,728,842
13	Water distribution, mains or services, buried	LF		#DIV/0!	\$0
14	Water storage tank, no foundation	Gal	460,000	\$1.63	\$750,318
15	Water treatment plant, no foundation	SF	2,500	\$590.47	\$1,476,176
16	Washeteria, no foundation	SF	600	\$761.47	\$456,885
17	Foundation - conventional, local gravel material	SF	0	#DIV/0!	\$0
18	Foundation - freeze back piles	SF	0	#DIV/0!	\$0
19	Foundation - thermosyphen stablized gravel pad	SF	7,300	\$90.27	\$658,951
20	Boardwalk	LF	0	#DIV/0!	\$0
21	Road, local gravel source	LF	0	#DIV/0!	\$0
22	Water source - surface water intake/ground water well	EA	1	\$185,500.02	\$185,500
24	Water heating system (boiler system in water treatment building)	EA	1	\$2,500.00	\$2,500
25	Water delivery piping system (from source to treatment plant)	LF	9,060	\$200.00	\$1,812,000
26	Fire suppression system (fire hydrants around the village)	EA	25	\$2,000.00	\$50,000
27	Solid waste site - closure, local material	Acre	5	\$38,034.22	\$190,171
28	Solid waste site - development, local material w/ equipment	Acre	10	\$90,929.16	\$909,292
29	Shop / Garage, no foundation, concrete floor	SF	400	\$383.45	\$153,382

Total Estimated Cost: \$17,599,384

Sitework Cost Estimate Tatchim Isua

Tatchim Isua Site Estimate

Site Preparation 1 Gravel Source Development 2 Site Design Survey 3 Mob/Demob 4 Site Pad Gravel (3 ft) 5 Road over Lagoon		1 1 1			LS		
2 Site Design Survey 3 Mob/Demob 4 Site Pad Gravel (3 ft)		1			1.0		
2 Site Design Survey 3 Mob/Demob 4 Site Pad Gravel (3 ft)		1					
3 Mob/Demob 4 Site Pad Gravel (3 ft)						\$10,000.00	\$10,000
4 Site Pad Gravel (3 ft)		1			LS	\$30,000.00	\$30,000
` /					LS	\$130,000	\$130,000
5 Road over Lagoon		488,186	13181022	3.00	CY	\$45	\$21,968,370
		0			LF		
6 Road to Site, Gravel		7,930			LF	\$450	\$3,568,500
7 Road to Runway, Gravel		1,640			LF	\$450	\$738,000
8 Road to Sewage Treatment, Gravel		300			LF	\$450	\$135,000
9 Road to Landfill, Gravel		7,460			LF	\$450	\$3,357,000
10 Road Bridge		30			LF	\$200	\$6,000
11 Road Culvert		300			LF	\$25	\$7,500
12 Hi-Density Insulation (8")		0			SY	\$45	
13 Geotextile Fabric		509,000			SY	\$10	\$5,090,000
14 Boat Staging Gravel (90 X 660 X 6)		13,200			CY	\$45	\$594,000
15 Barge Staging Gravel (208 X 208 X 5)		217,800			CY	\$45	\$9,801,000
16 Runway Gravel (6,000 lf)		221,000			CY	\$45	\$9,945,000
17 Camp Water line		3,700			LF	\$60	\$222,000
18 Storm Drainage Piping		14,000			LF	\$75	\$1,050,000
19 Storm Drainage Manholes		45			EA	\$3,000	\$135,000
20 Camp Security Fence		1,100			LF	\$20	\$22,000
21 Gravel Pad Labor/Season (Task Cost Ta	ab)	2				\$3,040,000	\$6,080,000
22 Village Construction Camp/Season		5				\$167,000	\$835,000
23 Airport Runway Labor/Seas. (Task Cost	Tab)	2				\$3,040,000	\$6,080,000
24 Airport Construction Camp/Season		2				\$167,000	\$334,000
25 Facility Maintenance Equipment		1			LS		\$283,900
Total Sitework Cost							\$70,422,27
26 Armor Rock		1 1	5.0	700.0	CY	\$50	\$175,000
		1	2.3	700.0	CY	\$20	\$32,200
27 2"-8" Rip-Rap 28 Erosion Fabric		1 1	3.4	700.0	SY	\$20 \$10	\$23,800
Total Errosion Protection Cost		 	3.4	700.0	31	φιυ	\$23,000

Assumptions

- 1 * Construction Camp Cost covers the entire construction season.
- 2 Road bridges will be precast, reinforced concrete manufactured off site and delivered
- 3 Gravel cost is delivered to site. Placement of gravel is included in Item 21 Gravel Pad Labor
- 4 Camp water line will be of different length depending on the location of the site. Length used is a guess from knowledge of site area.
- 5 All periods used for construction duration have been taken from Kivalina Master Relocation Schedule, Phase 6, dated 11/16/04
- Site survey shown here is for initial design survey. Survey required during construction is included in Items 22, 24. Design survey for airport is included.
- 7 Mob/Demob cost shown is a one-time cost associated with shipping equipment and camp to/from the site and set-up/tear-down at beginning/end of project.
- 8 Item 4 Site Pad Gravel is calculated using 2-depths; one using gravel alone and a second (Alt) using gravel over hi-density foam insulation.
- 9 Items 5, 6, 7, 8, 9 are gravel costs for material volume required to build roads to access the sites. Labor for placement is included in Items 22, 24
- 10 Items 10, 11 are guesses at the number of
- 11 Armor Rock shown in Item 26 is assumed to be minimum 4-man rock.
- 12 The 2"-8" rip-rap shown in Item 27 is fill behind Armor Rock.
- 13 Facility Maintenance Equipment item assumes

 Grader, 1999 Cat 140HNA
 \$145,000.00

 Backhoe/Loader, 2001 Cat 416C
 \$45,000.00

 Dozer, 1998 Cat D4CIIIXL
 \$54,000.00

 Dump Truck, 1998 Ford L9501
 \$39,900.00

 \$283,900.00

Equipment costs taken from internet web search of used equipment for sale

Estimated Costs

Tatchim Isua

Village

Kivalina Tatchim Isua

Item	Line Item	1	Estimated	Adjusted	Total
No.	Description		Quantity	Unit Cost	Cost
1	Household water and sewer plumbing	EA	100	\$20,267.59	\$2,026,759
	Sewage collection mains or services (gravity or force), buried	LF	13,000	\$87.81	\$1,141,574
	Sewage collection mains or services (gravity or force), above ground	LF	13,325	\$102.59	\$1,366,994
	Sewage lift station	EA	1	\$281,226.02	\$281,226
5	Vacuum sewer plant, no foundation	SF		#DIV/0!	\$0
6	Septic tank, and drainfield, individual household	EA	0	#DIV/0!	\$0
	Septic tank, community	EA	0	#DIV/0!	\$0
8	Drainfield, community	SF	0	#DIV/0!	\$0
9	Utilidors, above ground, including water and sewer, mains or services	LF	5,000	\$286.71	\$1,433,543
10	Sewage lagoon, barrow, local material	Acre	10	\$201,278.84	\$2,012,788
11	Sewage discharge works	LF	7,460	\$129.46	\$965,748
12	Water distribution, mains or services, above ground	LF	17,895	\$96.61	\$1,728,842
13	Water distribution, mains or services, buried	LF	13,000	\$86.08	\$1,119,049
14	Water storage tank, no foundation	Gal	460,000	\$1.63	\$750,318
	Water treatment plant, no foundation	SF	2,500	\$590.47	\$1,476,176
16	Washeteria, no foundation	SF	600	\$761.47	\$456,885
17	Foundation - conventional, local gravel material	SF	0	#DIV/0!	\$0
18	Foundation - freeze back piles	SF	0	#DIV/0!	\$0
19	Foundation - thermosyphen stablized gravel pad	SF	7,300	\$90.27	\$658,951
20	Boardwalk	LF	0	#DIV/0!	\$0
21	Road, local gravel source	LF	0	#DIV/0!	\$0
22	Water source - surface water intake/ground water well	EA	1	\$185,500.02	\$185,500
24	Water heating system (boiler system in water treatment building)	EA	1	\$2,500.00	\$2,500
25	Water delivery piping system (from source to treatment plant)	LF	5,125	\$200.00	\$1,025,000
26	Fire suppression system (fire hydrants around the village)	EA	25	\$2,000.00	\$50,000
27	Solid waste site - closure, local material	Acre	5	\$38,034.22	\$190,171
28	Solid waste site - development, local material w/ equipment	Acre	10	\$90,929.16	\$909,292
29	Shop / Garage, no foundation, concrete floor	SF	400	\$383.45	\$153,382

Total Estimated Cost: \$17,934,698

Sitework Cost Estimate Imnakuk Bluffs

Imnakuk Bluffs Site Estimate

Task/Item	Quantity	Units/LF	Item LF	Units	Unit Cost	Total
Site Preparation						
4 Occurs Development				1.0	040,000,00	040.000
1 Gravel Source Development	1			LS	\$10,000.00	\$10,000
2 Site Design Survey	1		ļ	LS	\$30,000.00	\$30,000
3 Mob/Demob	1 1 122 222			LS	\$130,000	\$130,000
4 Site Pad Gravel (9 ft)	1,489,890	40,227,029	9.00	CY	\$70	\$104,292,298
5 Road over Lagoon	6,095			LF		\$0
6 Road to Site, Gravel	10,425			LF	\$450	\$4,691,250
7 Road to Runway, Gravel	1,030			LF	\$450	\$463,500
8 Road to Sewage Treatment, Gravel	800			LF	\$450	\$360,000
9 Road to Landfill, Gravel	8,050			LF	\$450	\$3,622,500
10 Road Bridge	60			LF	\$200	\$12,000
11 Road Culvert	400			LF	\$25	\$10,000
12 Hi-Density Insulation (8")	0			SY	\$45	\$0
13 Geotextile Fabric	509,000			SY	\$10	\$5,090,000
14 Boat Staging Gravel (90 X 660 X 6)	13,200			CY	\$70	\$924,000
15 Barge Staging Gravel (208 X 208 X 5)	217,800			CY	\$70	\$15,246,000
16 River Dike	1	3.7	3,700.0	CY	\$50	\$684,500
17 Runway Gravel (6,000 lf)	221,000			CY	\$70	\$15,470,000
18 Camp Water line	500			LF	\$60	\$30,000
19 Storm Drainage Piping	14,000			LF	\$75	\$1,050,000
20 Storm Drainage Manholes	45		1	EA	\$3,000	\$135,000
21 Camp Security Fence	1,100		1	LF	\$20	\$22,000
22 Gravel Pad Labor/Season (Task Cost Tab)	2		1		\$3,040,000	\$6,080,000
23 Village Construction Camp/Season	5		1 1		\$167,000	\$835,000
24 Airport Runway Labor/Seas. (Task Cost Tab)	2		1		\$3,040,000	\$6,080,000
25 Airport Construction Camp/Season	2		†		\$167,000	\$334,000
26 Facility Maintenance Equipment	1		1	LS	, , , , , , , ,	\$283.900
Total Sitework Cost			1 1			\$165,885,948
		-	-	-		-
27 Armor Rock	1	5.0	700.0	CY	\$50	\$175,000
28 2"-8" Rip-Rap	1	2.3	700.0	CY	\$20	\$32,200
29 Erosion Fabric	1	3.4	700.0	SY	\$10	\$23,800
Total Errosion Protection Cost						\$231,000

Assumptions

- 1 * Construction Camp Cost covers the entire construction season.
- 2 Road bridges will be precast, reinforced concrete manufactured off site and delivered
- 3 Gravel cost is delivered to site. Placement of gravel is included in Item 21 Gravel Pad Labor
- 4 Camp water line will be of different length depending on the location of the site. Length used is a guess from knowledge of site area.
- 5 All periods used for construction duration have been taken from Kivalina Master Relocation Schedule, Phase 6, dated 11/16/04
- 6 Site survey shown here is for initial design survey. Survey required during construction is included in Items 22, 24. Design survey for airport is included.
- 7 Mob/Demob cost shown is a one-time cost associated with shipping equipment and camp to/from the site and set-up/tear-down at beginning/end of project.
- 8 Item 4 Site Pad Gravel is calculated using 2-depths; one using gravel alone and a second (Alt) using gravel over hi-density foam insulation.
- 9 Items 5, 6, 7, 8, 9 are gravel costs for material volume required to build roads to access the sites. Labor for placement is included in Items 22, 24
- 10 Items 10, 11 are guesses at the number of water course spanning structures required for the roads. These numbers will differ depending on the length of road
- 11 Armor Rock shown in Item 27 is assumed to be minimum 4-man rock.
- 12 The 2"-8" rip-rap shown in Item 28 is fill behind Armor Rock.
- 13 Item 16, River Dike is a directional dike constructed of Armor Rock at the mouth of the Kivalina River to redirect flow path to reduce siltation of dredged
- 14 Facility Maintenance Equipment item assumes contractor will leave used: backhoe/loader, road grader, small dozer, 10 YD dump truck for community use at Grader, 1999 Cat 140HNA \$145,000.00

Backhoe/Loader, 2001 Cat 416C \$45,000.00
Dozer, 1998 Cat D4CIIIXL \$54,000.00
Dump Truck, 1998 Ford L9501 \$39,900.00
\$283,900.00

Equipment costs taken from internet web search of used equipment for sale

Estimated Costs

Imnakuk Bluff

Village
Kivalina Imnakuk Bluff

Item	Line Item		Estimated	Adjusted	Total
No.	Description	Unit	Quantity	Unit Cost	Cost
1	Household water and sewer plumbing	EA	100	\$20,267.59	\$2,026,759
2	Sewage collection mains or services (gravity or force), buried	LF		#DIV/0!	\$0
3	Sewage collection mains or services (gravity or force), above ground	LF	13,325	\$102.59	\$1,366,994
4	Sewage lift station	EA	1	\$281,226.02	\$281,226
5	Vacuum sewer plant, no foundation	SF	2,500	\$487.80	\$1,219,492
6	Septic tank, and drainfield, individual household	EA	0	#DIV/0!	\$0
7	Septic tank, community	EA	0	#DIV/0!	\$0
8	Drainfield, community	SF	0	#DIV/0!	\$0
9	Utilidors, above ground, including water and sewer, mains or services	LF	5,000	\$286.71	\$1,433,543
10	Sewage lagoon, barrow, local material	Acre	10	\$201,278.84	\$2,012,788
11	Sewage discharge works	LF	3,345	\$149.03	\$498,520
12	Water distribution, mains or services, above ground	LF	17,895	\$96.61	\$1,728,842
13	Water distribution, mains or services, buried	LF		#DIV/0!	\$0
14	Water storage tank, no foundation	Gal	460,000	\$1.63	\$750,318
15	Water treatment plant, no foundation	SF	2,500	\$590.47	\$1,476,176
16	Washeteria, no foundation	SF	600	\$761.47	\$456,885
17	Foundation - conventional, local gravel material	SF	0	#DIV/0!	\$0
18	Foundation - freeze back piles	SF	0	#DIV/0!	\$0
19	Foundation - thermosyphen stablized gravel pad	SF	7,300	\$90.27	\$658,951
20	Boardwalk	LF	0	#DIV/0!	\$0
21	Road, local gravel source	LF	0	#DIV/0!	\$0
22	Water source - surface water intake/ground water well	EA	1	\$185,500.02	\$185,500
24	Water heating system (boiler system in water treatment building)	EA	1	\$2,500.00	\$2,500
25	Water delivery piping system (from source to treatment plant)	LF	5,680	\$200.00	\$1,136,000
26	Fire suppression system (fire hydrants around the village)	EA	25	\$2,000.00	\$50,000
27	Solid waste site - closure, local material	Acre	5	\$38,034.22	\$190,171
28	Solid waste site - development, local material w/ equipment	Acre	10	\$90,929.16	\$909,292
29	Shop / Garage, no foundation, concrete floor	SF	400	\$383.45	\$153,382

Total Estimated Cost: \$16,537,339

Sitework Cost Estimate Kiniktuuraq

Kiiktuuraq Site Estimate

Task/Item	Quantity	Units/LF	LF of Item	Units	Unit Cost	Total
Site Preparation						
4 October Development				LS	£40.000	040,000
1 Gravel Source Development	1				\$10,000	\$10,000
2 Site Design Survey	1			LS	\$30,000	\$30,000
3 Mob/Demob	1 400 000	10.007.000.10	0.00	LS CY	\$130,000	\$130,000
4 Site Pad Gravel (9 ft)	1,489,890	40,227,029.13	9.00		\$70	\$104,292,298
5 Road over Lagoon	0			LF		
6 Road to Site, Gravel	0			LF	\$450	\$0
7 Road to Runway, Gravel	15,815			LF	\$450	\$7,116,750
8 Road to Sewage Treatment, Gravel	540			LF	\$450	\$243,000
9 Road to Landfill, Gravel	600			LF	\$450	\$270,000
10 Road Bridge	60			LF	\$200	\$12,000
11 Road Culvert	200			LF	\$25	\$5,000
12 Hi-Density Insulation (8")	0			SY	\$45	
13 Geotextile Fabric	509,000			SY	\$10	\$5,090,000
14 Boat Staging Gravel (90 X 660 X 6)	13,200			CY	\$70	\$924,000
15 Barge Staging Gravel (208 X 208 X 5)	217,800			CY	\$70	\$15,246,000
16 River Dike	1	3.7	0.0	CY	\$50	
17 Runway Gravel (6,000 lf)	221,000			CY	\$70	\$15,470,000
18 Camp Water line	500			LF	\$60	\$30,000
19 Storm Drainage Piping	14,000			LF	\$75	\$1,050,000
20 Storm Drainage Manholes	45			EA	\$3,000	\$135,000
21 Camp Security Fence	1,100			LF	\$20	\$22,000
22 Gravel Pad Labor/Season (Task Cost Tab)	2				\$3,040,000	\$6,080,000
23 Village Construction Camp/Season	5				\$167,000	\$835,000
24 Airport Runway Labor/Seas. (Task Cost Tab)	2				\$3,040,000	\$6,080,000
25 Airport Construction Camp/Season	2				\$167,000	\$334,000
26 Facility Maintenance Equipment	1		†	LS	, , , , , , , , , , , , , , , , , , , ,	\$283,900
Total Sitework Cost			1	1	1 1	\$163,688,94
	<u> </u>	T.				************
27 Armor Rock	1	5.0	7920.0	CY	\$50	\$1,980,000
28 2"-8" Rip-Rap	1	2.3	7920.0	CY	\$20	\$364,320
29 Erosion Fabric	1	3.4	7920.0	SY	\$10	\$269,280
Total Errosion Protection Cost				1 1		\$2,613,60

Assumptions

- 1 * Construction Camp Cost covers the entire construction season.
- 2 Road bridges will be precast, reinforced concrete manufactured off site and delivered
- 3 Gravel cost is delivered to site. Placement of gravel is included in Item 21 Gravel Pad Labor
- 4 Camp water line will be of different length depending on the location of the site. Length used is a guess from knowledge of site area.
- 5 All periods used for construction duration have been taken from Kivalina Master Relocation Schedule, Phase 6, dated 11/16/04
- 6 Site survey shown here is for initial design survey. Survey required during construction is included in Items 20,22. Design survey for airport is included.
- 7 Mob/Demob cost shown is a one-time cost associated with shipping equipment and camp to/from the site and set-up/tear-down at beginning/end of project.
- 8 Item 4 Site Pad Gravel is calculated using 2-depths; one using gravel alone and a second (Alt) using gravel over hi-density foam insulation.
- 9 Items 5, 6, 7, 8, 9 are gravel costs for material volume required to build roads to access the sites. Labor for placement is included in Items 20, 22
- 10 Items 10, 11 are guesses at the number of water course spanning structures required for the roads. These numbers will differ depending on the length of road needed.
- 11 Armor Rock shown in Item 27 is assumed to be minimum 4-man rock.
- 12 The 2"-8" rip-rap shown in Item 28 is fill behind Armor Rock.
- 13 Item 16, River Dike is a directional dike constructed of Armor Rock at the mouth of the Kivalina River to redirect flow path to reduce siltation of dredged channel.
- 14 Facility Maintenance Equipment item assumes contractor will leave used: backhoe/loader, road grader, small dozer, 10 YD dump truck for community use at comonstuction

Grader, 1999 Cat 140HNA \$145,000.00
Backhoe/Loader, 2001 Cat 416C \$45,000.00
Dozer, 1998 Cat D4CHIXL \$54,000.00
Dump Truck, 1998 Ford L9501 \$283,900.00
\$283,900.00
\$422,800.00

Equipment costs taken from internet web search of used equipment for sale

Estimated Costs

Kinituuraq

Village Kivalina Kinituuraq

Item	Line Item		Estimated	Adjusted	Total
No.	Description	Unit	Quantity	Unit Cost	Cost
1	Household water and sewer plumbing	EA	100	\$20,267.59	\$2,026,759
2	Sewage collection mains or services (gravity or force), buried	LF		#DIV/0!	\$0
3	Sewage collection mains or services (gravity or force), above ground	LF	13,325	\$102.59	\$1,366,994
4	Sewage lift station	EA	1	\$281,226.02	\$281,226
5	Vacuum sewer plant, no foundation	SF	1	\$34,746.09	\$34,746
6	Septic tank, and drainfield, individual household	EA	0	#DIV/0!	\$0
7	Septic tank, community	EA	0	#DIV/0!	\$0
8	Drainfield, community	SF	0	#DIV/0!	\$0
9	Utilidors, above ground, including water and sewer, mains or services	LF	5,000	\$286.71	\$1,433,543
10	Sewage lagoon, barrow, local material	Acre	10	\$201,278.84	\$2,012,788
11	Sewage discharge works	LF	10,575	\$124.77	\$1,319,433
12	Water distribution, mains or services, above ground	LF	17,895	\$96.61	\$1,728,842
13	Water distribution, mains or services, buried	LF		#DIV/0!	\$0
14	Water storage tank, no foundation	Gal	460,000	\$1.63	\$750,318
15	Water treatment plant, no foundation	SF	2,500	\$590.47	\$1,476,176
16	Washeteria, no foundation	SF	600	\$761.47	\$456,885
17	Foundation - conventional, local gravel material	SF	0	#DIV/0!	\$0
18	Foundation - freeze back piles	SF	0	#DIV/0!	\$0
19	Foundation - thermosyphen stablized gravel pad	SF	7,300	\$90.27	\$658,951
20	Boardwalk	LF	0	#DIV/0!	\$0
21	Road, local gravel source	LF	0	#DIV/0!	\$0
22	Water source - surface water intake/ground water well	EA	1	\$185,500.02	\$185,500
24	Water heating system (boiler system in water treatment building)	EA	1	\$2,500.00	\$2,500
25	Water delivery piping system (from source to treatment plant)	LF	17,000	\$200.00	\$3,400,000
26	Fire suppression system (fire hydrants around the village)	EA	25	\$2,000.00	\$50,000
27	Solid waste site - closure, local material	Acre	5	\$38,034.22	\$190,171
28	Solid waste site - development, local material w/ equipment	Acre	10	\$90,929.16	\$909,292
29	Shop / Garage, no foundation, concrete floor	SF	400	\$383.45	\$153,382

Total Estimated Cost: \$18,437,506

Sitework Cost Estimate Igrugaivik

Igrugaivik Site Estimate

Task/Item	1	Quantity	Units/LF	LF of Item	Units	Unit Cost	Total
Site Prep	aration						
	ource Development	1			LS	\$10,000	\$10,000
	gn Survey	1			LS	\$30,000	\$30,000
3 Mob/Dem	ob	1			LS	\$130,000	\$130,000
4 Site Pad	Gravel (9 ft)	1,489,890	40227029	9.00	CY	\$70	\$104,292,298
5 Road ove	r Lagoon	0			LF		
6 Road to S	Site, Gravel	6,470			LF	\$450	\$2,911,500
7 Road to F	Runway, Gravel	4,495			LF	\$450	\$2,022,750
8 Road to S	Sewage Treatment, Gravel	1,385			LF	\$450	\$623,250
9 Road to L	andfill, Gravel	in Sewage			LF	\$450	
10 Road Brid	dge	90			LF	\$200	\$18,000
11 Road Cul	vert	300			LF	\$25	\$7,500
12 Hi-Densit	y Insulation (8")	0			SY	\$45	
13 Geotextile	e Fabric	509,000			SY	\$10	\$5,090,000
14 Boat Stag	jing Gravel (90 X 660 X 6)	13,200			CY	\$70	\$924,000
15 Barge Sta	aging Gravel (208 X 208 X 5)	217,800			CY	\$70	\$15,246,000
16 River Dike	e	1	3.7	0.0	CY	\$50	
17 Runway (Gravel (4,000 lf)	266,000			CY	\$70	\$18,620,000
18 Camp Wa	ater line	500			LF	\$60	\$30,000
19 Storm Dra	ainage Piping	14,000			LF	\$75	\$1,050,000
20 Storm Dra	ainage Manholes	45			EA	\$3,000	\$135,000
21 Camp Se	curity Fence	1,100			LF	\$20	\$22,000
22 Gravel Pa	ad Labor/Season (Task Cost Tab)	2				\$3,040,000	\$6,080,000
23 Village Co	onstruction Camp/Season	5				\$167,000	\$835,000
24 Airport Ru	unway Labor/Seas. (Task Cost Tab)	2				\$3,040,000	\$6,080,000
25 Airport Co	onstruction Camp/Season	2				\$167,000	\$334,000
26 Facility M	aintenance Equipment	1			LS		\$283,900
Total Site	ework Cost						\$164,775,198
27 Armor Ro		1	5.0	3168.0	CY	\$50	\$792,000
28 2"-8" Rip-	Rap	1	2.3	3168.0	CY	\$20	\$145,728
29 Erosion F	abric	1	3.4	3168.0	SY	\$10	\$107,712
Total Err	osion Protection Cost						\$1,045,440

Assumptions

- 1 * Construction Camp Cost covers the entire construction season.
- 2 Road bridges will be precast, reinforced concrete manufactured off site and delivered
- 3 Gravel cost is delivered to site. Placement of gravel is included in Item 26 Gravel Pad Labor
- 4 Camp water line will be of different length depending on the location of the site. Length used is a guess from knowledge of site area.
- 5 All periods used for construction duration have been taken from Kivalina Master Relocation Schedule, Phase 6, dated 11/16/04
- 6 Site survey shown here is for initial design survey. Survey required during construction is included in Items 22, 24. Design survey for airport is included.
- 7 Mob/Demob cost shown is a one-time cost associated with shipping equipment and camp to/from the site and set-up/tear-down at beginning/end of project.
- 8 Item 4 Site Pad Gravel is calculated using 2-depths; one using gravel alone and a second (Alt) using gravel over hi-density foam insulation.
- 9 Items 5, 6, 7, 8, 9 are gravel costs for material volume required to build roads to access the sites. Labor for placement is included in Items 22, 24
- 10 Items 10, 11 are guesses at the number of water course spanning structures required for the roads. These numbers will differ depending on the length of road
- 11 Armor Rock shown in Item 27 is assumed to be minimum 4-man rock.
- 12 The 2"-8" rip-rap shown in Item 28 is fill behind Armor Rock.
- 13 Item 16, River Dike is a directional dike constructed of Armor Rock at the mouth of the Kivalina River to redirect flow path to reduce siltation of dredged channel.
- 14 Facility Maintenance Equipment item assumes contractor will leave used: backhoe/loader, road grader, small dozer, 10 YD dump truck for community use at

Grader, 1999 Cat 140HNA \$145,000.00
Backhoe/Loader, 2001 Cat 416C \$45,000.00
Dozer, 1998 Cat D4CIIIXL \$54,000.00
Dump Truck, 1998 Ford L9501 \$39,900.00
\$283,900.00

Equipment costs taken from internet web search of used equipment for sale

Estimated Costs

Igrugaivik

VillageKivalina Igrugaivik

Item	Line Item		Estimated	Adjusted	Total
No.	Description	Unit	Quantity	Unit Cost	Cost
1	Household water and sewer plumbing	EA	100	\$20,267.59	\$2,026,759
2	Sewage collection mains or services (gravity or force), buried	LF		#DIV/0!	\$0
3	Sewage collection mains or services (gravity or force), above ground	LF	13,325	\$102.59	\$1,366,994
4	Sewage lift station	EA	1	\$281,226.02	\$281,226
5	Vacuum sewer plant, no foundation	SF	2,500	\$487.80	\$1,219,492
6	Septic tank, and drainfield, individual household	EA	0	#DIV/0!	\$0
7	Septic tank, community	EA	0	#DIV/0!	\$0
8	Drainfield, community	SF	0	#DIV/0!	\$0
9	Utilidors, above ground, including water and sewer, mains or services	LF	5,000	\$286.71	\$1,433,543
10	Sewage lagoon, barrow, local material	Acre	10	\$201,278.84	\$2,012,788
11	Sewage discharge works	LF	3,385	\$148.61	\$503,062
12	Water distribution, mains or services, above ground	LF	17,895	\$96.61	\$1,728,842
13	Water distribution, mains or services, buried	LF		#DIV/0!	\$0
14	Water storage tank, no foundation	Gal	460,000	\$1.63	\$750,318
15	Water treatment plant, no foundation	SF	2,500	\$590.47	\$1,476,176
16	Washeteria, no foundation	SF	600	\$761.47	\$456,885
17	Foundation - conventional, local gravel material	SF	0	#DIV/0!	\$0
18	Foundation - freeze back piles	SF	0	#DIV/0!	\$0
19	Foundation - thermosyphen stablized gravel pad	SF	7,300	\$90.27	\$658,951
20	Boardwalk	LF	0	#DIV/0!	\$0
21	Road, local gravel source	LF	0	#DIV/0!	\$0
22	Water source - surface water intake/ground water well	EA	1	\$185,500.02	\$185,500
24	Water heating system (boiler system in water treatment building)	EA	1	\$2,500.00	\$2,500
25	Water delivery piping system (from source to treatment plant)	LF	8,475	\$200.00	\$1,695,000
26	Fire suppression system (fire hydrants around the village)	EA	25	\$2,000.00	\$50,000
27	Solid waste site - closure, local material	Acre	5	\$38,034.22	\$190,171
28	Solid waste site - development, local material w/ equipment	Acre	10	\$90,929.16	\$909,292
29	Shop / Garage, no foundation, concrete floor	SF	400	\$383.45	\$153,382

Total Estimated Cost: \$17,100,881

Sitework Cost Estimate Kuugruak

Kuugruak Site Estimate

Task/Item	Quantity	Units/LF	LF of Item	Units	Unit Cost	Total
Site Preparation						
Gravel Source Development	1			LS	\$10,000	\$10,000
2 Site Design Survey	1			LS	\$30,000	\$30,000
3 Mob/Demob	1			LS	\$130,000	\$130,000
4 Site Pad Gravel (9 ft)	1,489,890	40227029	9.00	CY	\$70	\$104,292,298
5 Road over Lagoon	0			LF		
6 Road to Site, Gravel	9,330			LF	\$450	\$4,198,500
7 Road to Runway, Gravel	7,775			LF	\$450	\$3,498,750
8 Road to Sewage Treatment, Gravel	1,815			LF	\$450	\$816,750
9 Road to Landfill, Gravel	475			LF	\$450	\$213,750
10 Road Bridge	120			LF	\$200	\$24,000
11 Road Culvert	200			LF	\$25	\$5,000
12 Hi-Density Insulation (8")	0			SY	\$45	
13 Geotextile Fabric	509,000			SY	\$10	\$5,090,000
14 Boat Staging Gravel (90 X 660 X 6)	13,200			CY	\$70	\$924,000
15 Barge Staging Gravel (208 X 208 X 5)	217,800			CY	\$70	\$15,246,000
16 Runway Gravel (6,000 lf)	221,000			CY	\$70	\$15,470,000
17 Camp Water line	500			LF	\$60	\$30,000
18 Storm Drainage Piping	14,000			LF	\$75	\$1,050,000
19 Storm Drainage Manholes	45			EA	\$3,000	\$135,000
20 Camp Security Fence	1,100			LF	\$20	\$22,000
21 Gravel Pad Labor/Season (Task Cost Tab)	2				\$3,040,000	\$6,080,000
22 Village Construction Camp/Season	5				\$167,000	\$835,000
23 Airport Runway Labor/Seas. (Task Cost Tab)	2				\$3,040,000	\$6,080,000
24 Airport Construction Camp/Season	2				\$167,000	\$334,000
25 Facility Maintenance Equipment	1			LS		\$283,900
Total Sitework Cost						\$164,798,948
26 Armor Rock	1	5.0	8975.0	CY	\$50	\$2,243,750
27 2"-8" Rip-Rap	1	2.3	8975.0	CY	\$20	\$412,850
28 Erosion Fabric	1	3.4	8975.0	SY	\$10	\$305,150
Total Errosion Protection Cost	_					\$2,961,750

Assumptions

- 1 * Construction Camp Cost covers the entire construction season.
- 2 Road bridges will be precast, reinforced concrete manufactured off site and delivered
- 3 Gravel cost is delivered to site. Placement of gravel is included in Item 26 Gravel Pad Labor
- 4 Camp water line will be of different length depending on the location of the site. Length used is a guess from knowledge of site area.
- 5 All periods used for construction duration have been taken from Kivalina Master Relocation Schedule, Phase 6, dated 11/16/04
- 6 Site survey shown here is for initial design survey. Survey required during construction is included in Items 22, 24. Design survey for airport is included.
- 7 Mob/Demob cost shown is a one-time cost associated with shipping equipment and camp to/from the site and set-up/tear-down at beginning/end of project.
- 8 Item 4 Site Pad Gravel is calculated using 2-depths; one using gravel alone and a second (Alt) using gravel over hi-density foam insulation.
- 9 Items 5, 6, 7, 8, 9 are gravel costs for material volume required to build roads to access the sites. Labor for placement is included in Items 22, 24
- 10 Items 10, 11 are guesses at the number of water course spanning structures required for the roads. These numbers will differ depending on the length of road
- 11 Armor Rock shown in Item 26 is assumed to be minimum 4-man rock.
- 12 The 2"-8" rip-rap shown in Item 27 is fill behind Armor Rock.
- 13 Facility Maintenance Equipment item assumes contractor will leave used: backhoe/loader, road grader, small dozer, 10 YD dump truck for community use at comonstruction completion

 Grader, 1999 Cat 140HNA
 \$145,000.00

 Backhoe/Loader, 2001 Cat 416C
 \$45,000.00

 Dozer, 1998 Cat D4CIIIXL
 \$54,000.00

 Dump Truck, 1998 Ford L9501
 \$39,900.00

 \$283,900.00

Equipment costs taken from internet web search of used equipment for sale

Estimated Costs

Kuugruaq

Village Kivalina Kuugruaq

Item	Line Item		Estimated	Adjusted	Total
No.	Description	Unit	Quantity	Unit Cost	Cost
1	Household water and sewer plumbing	EA	100	\$20,267.59	\$2,026,759
2	Sewage collection mains or services (gravity or force), buried	LF		#DIV/0!	\$0
3	Sewage collection mains or services (gravity or force), above ground	LF	13,325	\$102.59	\$1,366,994
4	Sewage lift station	EA	1	\$281,226.02	\$281,226
5	Vacuum sewer plant, no foundation	SF	1	\$34,746.09	\$34,746
6	Septic tank, and drainfield, individual household	EA	0	#DIV/0!	\$0
7	Septic tank, community	EA	0	#DIV/0!	\$0
8	Drainfield, community	SF	0	#DIV/0!	\$0
9	Utilidors, above ground, including water and sewer, mains or services	LF	5,000	\$286.71	\$1,433,543
10	Sewage lagoon, barrow, local material	Acre	10	\$201,278.84	\$2,012,788
11	Sewage discharge works	LF	4,645	\$139.10	\$646,125
12	Water distribution, mains or services, above ground	LF	17,895	\$96.61	\$1,728,842
13	Water distribution, mains or services, buried	LF		#DIV/0!	\$0
14	Water storage tank, no foundation	Gal	460,000	\$1.63	\$750,318
	Water treatment plant, no foundation	SF	2,500	\$590.47	\$1,476,176
16	Washeteria, no foundation	SF	600	\$761.47	\$456,885
	Foundation - conventional, local gravel material	SF	0	#DIV/0!	\$0
18	Foundation - freeze back piles	SF	0	#DIV/0!	\$0
19	Foundation - thermosyphen stablized gravel pad	SF	7,300	\$90.27	\$658,951
20	Boardwalk	LF	0	#DIV/0!	\$0
21	Road, local gravel source	LF	0	#DIV/0!	\$0
22	Water source - surface water intake/ground water well	EA	1	\$185,500.02	\$185,500
24	Water heating system (boiler system in water treatment building)	EA	1	\$2,500.00	\$2,500
25	Water delivery piping system (from source to treatment plant)	LF	3,790	\$200.00	\$758,000
26	Fire suppression system (fire hydrants around the village)	EA	25	\$2,000.00	\$50,000
27	Solid waste site - closure, local material	Acre	5	\$38,034.22	\$190,171
28	Solid waste site - development, local material w/ equipment	Acre	10	\$90,929.16	\$909,292
29	Shop / Garage, no foundation, concrete floor	SF	400	\$383.45	\$153,382

Total Estimated Cost: \$15,122,198

Sitework Cost Estimate Kivalina

Kivalina Site Estimate

	Task/Item		Quantity	Units/LF	Item LF	Units		Unit Cost	—	Total
	Site Preparation								_	
	Site Preparation	1								
1	Gravel Source Development		1			LS		\$10,000.00		\$10,000
2	Site Design Survey		1			LS		\$10,000.00		\$10,000
3	Mob/Demob		1			LS		\$130,000		\$130,000
4	Site Pad Gravel (6.5 ft)		1,068,383	28,846,350	6.50	CY		\$70		\$74,786,832
5	Move Buildings	(Figured int	o Labor)							
6	Road to Site Gravel		0			LF		\$450		
7	Road to Runway Gravel		0			LF		\$450		
8	Road Bridge		0			LF		\$200		
9	Road Culvert		0			LF		\$25		
10	Hi-Density Insulation (8")		0			SY		\$45		
11	Geotextile Fabric		97,000			SY		\$10		\$970,000
12	Boat Staging Gravel (90 X 660 X 6)		13,200			CY		\$70		\$924,000
13	Barge Staging Gravel (208 X 208 X 5)		1			CY		\$70		\$70
14	Runway Gravel (6,000 lf)		221,000			CY		\$70		\$15,470,000
15	Camp Water Fill		1			LS		\$60		\$60
16	Storm Drainage Piping		14,000			LF		\$75		\$1,050,000
17	Storm Drainage Manholes		45			EA		\$3,000		\$135,000
18	Camp Security Fence		1,100			LF		\$20		\$22,000
19	Gravel Pad Labor/Season (Task Cost Tab)		2					\$3,160,000		\$6,320,000
	Village Construction Camp/Season		5					\$453,000		\$2,265,000
	Airport Runway Labor/Seas. (Task Cost Tab)	1	2					\$3,160,000		\$6,320,000
22	Airport Construction Camp/Season	Ī	2					\$453,000		\$906,000
23	Facility Maintenance Equipment	Ī	1			LS				\$283,900
	Total Sitework Cost	Ī								\$109,602,862
					<u> </u>	-		-		
24	Armor Rock	1 1	1	5.0	4,285.0	CY		\$50		\$1,071,250
	, umor 1,000	_		0.0	.,_50.0	<u>~ . </u>	<u> </u>	400		ψ·,σ· ·,=σσ

-	Total Errosion Protection Cost						\$7,151,550
28	Sheet Pile Wall	1	20.00	3,825.0	LF	\$75	\$5,737,500
27	Erosion Fabric	1	3.4	4,285.0	SY	\$10	\$145,690
26	2"-8" Rip-Rap	1	2.3	4,285.0	CY	\$20	\$197,110
24	Armor Rock	1	5.0	4,285.0	CY	\$50	 \$1,071,250

Assumptions

- 1 * Construction Camp Cost covers the entire construction season.
- ${\bf 2} \,\, {\sf Road} \,\, {\sf bridges} \,\, {\sf will} \,\, {\sf be} \,\, {\sf precast}, \, {\sf reinforced} \,\, {\sf concrete} \,\, {\sf manufactured} \,\, {\sf off} \,\, {\sf site} \,\, {\sf and} \,\, {\sf delivered}$
- 3 Gravel cost is delivered to site. Placement of gravel is included in Item 19 Gravel Pad Labor
- 4 Camp water line will be of different length depending on the location of the site. Length used is a guess from knowledge of site area.
- 5 All periods used for construction duration have been taken from Kivalina Master Relocation Schedule, Phase 6, dated 11/16/04
- 6 Site survey shown here is for initial design survey. Survey required during construction is included in Items 20, 22. Design survey for airport is included.
- 7 Mob/Demob cost shown is a one-time cost associated with shipping equipment and camp to/from the site and set-up/tear-down at beginning/end of project.
- 8 Item 4 Site Pad Gravel is calculated using 2-depth; one using gravel alone and a second using gravel over hi-density foam insulation.
- 9 Items 5, 6 are gravel costs for material volume required to build roads to access the sites. Labor for placement is included in Items 19, 21.
- 10 Items 7, 8 are guesses at the number of water course spanning structures required for the roads. These numbers will differ depending on the length of road needed.
- 11 Armor Rock shown in Item 24 is assumed to be minimum 4-man rock.
- 12 Sheet pile is assumed to be vinyl, not steel. We don't have a lot of soil behind it and it doesn't corrode.
- 13 The 2"-8" rip-rap shown in Item 26 is fill behind Armor Rock.
- 14 Facility Maintenance Equipment item assumes contractor will leave used: backhoe/loader, road grader, small dozer, 10 YD dump truck for community use at construction completion.

 Grader, 1999 Cat 140HNA
 \$145,000.00

 Backhoe/Loader, 2001 Cat 416C
 \$45,000.00

 Dozer, 1998 Cat D4CIIIXL
 \$54,000.00

 Dump Truck, 1998 Ford L9501
 \$39,900.00

 \$283,900.00

Equipment prices obtained from in internet search of equipment for sale.

15 Sheet piling is assumed to be driven 14 ft into the ground and extend 6 ft above existing grade for a total height of 14 ft

Estimated Costs

Village Kivalina

Item	Line Item	1	Estimated	Adjusted	Total
No.	Description		Quantity	Unit Cost	Cost
1	Household water and sewer plumbing	EA	100	\$20,267.59	\$2,026,759
	Sewage collection mains or services (gravity or force), buried	LF	4,590	\$109.12	\$500,878
	Sewage collection mains or services (gravity or force), above ground	LF	0	#DIV/0!	\$0
	Sewage lift station	EA	4	\$183,282.02	\$733,128
5	Vacuum sewer plant, no foundation	SF	2,500	\$487.80	\$1,219,492
6	Septic tank, and drainfield, individual household	EA	0	#DIV/0!	\$0
7	Septic tank, community	EA	0	#DIV/0!	\$0
8	Drainfield, community	SF	0	#DIV/0!	\$0
9	Utilidors, above ground, including water and sewer, mains or services	LF	5,000	\$286.71	\$1,433,543
10	Sewage lagoon, barrow, local material	Acre	10	\$201,278.84	\$2,012,788
11	Sewage ocean outfall	LF	500	\$350.98	\$175,491
12	Water distribution, mains or services, above ground	LF	4,090	\$107.81	\$440,929
	Water distribution, mains or services, buried	LF	13,000	\$86.08	\$1,119,049
14	Water storage tank, no foundation	Gal	460,000	\$1.63	\$750,318
15	Water treatment plant, no foundation	SF	2,500	\$590.47	\$1,476,176
16	Washeteria, no foundation	SF	800	\$747.19	\$597,756
17	Foundation - conventional, local gravel material	SF	750	\$334.70	\$251,026
18	Foundation - freeze back piles	SF	0	#DIV/0!	\$0
	Foundation - thermosyphen stablized gravel pad	SF	0	#DIV/0!	\$0
	Boardwalk	LF	0	#DIV/0!	\$0
21	Road, local gravel source	LF	0	#DIV/0!	\$0
	Water source - surface water intake	EA	1	\$185,500.02	\$185,500
	Water source - ground water well	EA	0	#DIV/0!	\$0
	Water heating system (boiler system in water treatment building)	EA	1	\$2,500.00	\$2,500
	Water delivery piping system (from source to treatment plant)	LF	10,000	\$200.00	\$2,000,000
	Fire suppression system (fire hydrants around the village)	EA	25	\$2,000.00	\$50,000
	Solid waste site - closure, local material	Acre	5	\$38,034.22	\$190,171
	Solid waste site - development, local material w/ equipment	Acre	10	\$90,929.16	\$909,292
29	Shop / Garage, no foundation, concrete floor	SF	400	\$383.45	\$153,382

Total Estimated Cost: \$16,228,178

6/19/2006

Kivalina Relocation Project

Description	Unit Cost	Quantity			Total
	CAPITAL C	OSTS			
Hovercraft Cost					
Base Cost On Board Spares Kit Air Conditioning Shipping Pallet Shrink Wrap Spreader Bar to Lift Craft Boarding Ladder w/Handrail	\$329,970.00 \$1,554.00 \$6,121.00 \$739.00 \$585.00 \$1,183.00 \$616.00	3 3 3 3 3 3		-	\$989,910.00 \$4,662.00 \$18,363.00 \$2,217.00 \$1,755.00 \$3,549.00 \$1,848.00
					ψ1,022,00 4 .00
Truck Shipping Cost Barge Shipping Cost	Weight (lbs) 9,325.00 9,325.00		# Hundred Weight 93.25 93.25	Rate per C-weight \$50.00 \$150.00	\$4,662.50 \$13,987.50 \$18,650.00
Technical Costs					
Technical Assistance (Technicians + Instructor)	Unit Cost \$6,000.00	Units 3	Quantity 1		\$18,000.00
Airfare RT Room & Board Miscellaneous	\$1,750.00 \$75.00	3	1 15	-	\$5,250.00 \$3,375.00 \$500.00 \$27,125.00
Hanger Costs					
Storage and Maintenance Hanger	Unit Cost \$300.00	Units 5000	Quantity 1		\$1,500,000.00
Total Capital Costs					\$2,568,079.00

OPERATION & MAINTENANCE COSTS

			Interval	Arctic*	
Annual Maintenance	Unit Cost	Quantity	Hours	Operations	Total
Engine					
Major Overhaul (Arctic Conditions)	\$14,166.67	1	8000	\$1.77	\$5,814.45
Adjust Engine Valve Clearance	\$41.67	1	1000	\$0.04	\$131.40
Routine Oil Change (Liters)	\$2.50	22	250	\$0.22	\$722.70
Routine Oil Filter Change	\$39.17	1	250	\$0.16	\$525.60
Routine Air Filter Change	\$84.17	1	2000	\$0.04	\$131.40
Thrust Unit					
Replace Upper Pylon Bearings	\$483.33	2	4000	\$0.24	\$793.87
Replace Lower Pylon Bearings	\$325.83	2	4000	\$0.16	\$535.18
Replace Drive Belt	\$966.96	1	4000	\$0.24	\$794.12
Fuel System					
Fuel Consumption (Gals)	\$3.00	7	1	\$21.00	\$68,985.00
Fuel Filter	\$20.83	1	500	\$0.04	\$136.85
Coolong System					
Coolant (Gals)	\$7.10	10.58	12000	\$0.01	\$20.56
Coolant Filter	\$47.50	1	500	\$0.10	\$312.08
Hydraulic System 1 (Lift Fans)					
Hydraulic Fluid	\$6.77	72	4000	\$0.12	\$400.31
Filter	\$69.17	1	1000	\$0.07	\$227.22
Upper & Lower Fan Bearings	\$175.50	4	4000	\$0.18	\$576.52
Hydraulic System 2					
(Coolant Fans, Prop, Rudders & Elevators)					
Hydraulic Fluid	\$6.77	72	4000	\$0.12	\$400.31
Filter	\$69.17	1	1000	\$0.07	\$227.22
Skirt Wear (Over Calm Water)	Not Used				1
Standard Segment	\$40.00	150	800	\$7.50	\$0.00
Stern Segments	\$70.00	25	800	\$2.19	\$0.00
Skirt Wear (Over Smooth Ice)					
Standard Segment	\$40.00	150	400	\$15.00	\$49,275.00
Stern Segments	\$70.00	25	400	\$4.38	\$14,371.88
See Note X.					
Miscellaneous					
Repair Allowance for Instruments, lights	\$16.67	1	1	\$16.67	\$18,253.65
sides, skirt loop, etc					
Total Direct Annual O&M Cost for 3 HC's					\$162,635.31 per y

Total Direct Annual O&M Cost for 3 HC's	\$162,635.31 per yr
Total Direct 3-year O&M Cost for 3 HC's	\$487,905.94 per 3-yrs

Capital + 3yr-O&M Costs

\$3,055,984.94 TOTAL

Transportation System Costs

			Qty of	
Estimated Annual Use Hours	Hours/Day	Days	Hovercraft	Total
	3.00	365	3	3285

Assumptions

- * Units are in dollars/operated hour
- 1. Room and board in Kivalina will consist of the three VanAir reps sleeping in the school, as usual, and eating out of the teachers lounge kitchen, fixing their own food.
- 2. Instruction to teach a max of 9 people (3/craft) to operate the hovercraft is included in the purchase price
- 3. Transportation costs are estimated to be \$50/hundredweight by truck from Ontario to Anchorage. Barge costs have been estimated off the ANTHC cost estimating sheet by using the freight cost of a single family septic tank & drainfield.
- X. Skirt wear rate will vary depending on surface conditions and pilot technique
- Y. Local costs for consumables will vary
- Z. Local operating conditions may affect service interval

Construction Camp Cost Estimate Kivalina Site Task Costs

					Mivaiiia	Sile Task Cusis					
										First	Ea Other
	Task/Item	Quant	ty	Capital Cost	Machine Cost/hr	Personnel Cost/hr	Hours/wk	Weekly Total	Months	Season Total	Season Total
	Camp Cost	Quant	ty	Capital Cost	Machine Cost/hr	Personnel Cost/hr	Hours/wk	Weekly Total	Months	Season Total	Season Total
						Installation Cost LS					
	ATCO Trailers										
13	Camp Start-up	1		\$10,000.00						\$10,000	\$10,000
14	Sleeping	2		\$1,000.00						\$1,000	\$0
15	Shower/Clothes Washing/Dining	1		\$1,000.00						\$1,000	\$0
16	Office	1		\$1,000.00						\$1,000	\$0
17	Storage Conex	3		\$1,000.00						\$1,000	\$0
18	Food (per weekly meals)	504		\$5.00				\$2,520	6	\$60,480	\$60,480
19	Power Genset	1		\$0.00		\$5,000.00			6	\$5,000	\$1,000
	Fuel Tankage	1		\$0.00		\$3,000.00			6	\$3,000	\$1,000
	Operating Fuel (gals/hr)	8			\$3.00		168	\$4,032	6	\$24,192	\$24,192
22	Telephone	1		\$1,000.00		\$2,500.00			6	\$2,500	\$500
23	Develop Raw Water Source	1			\$2,500.00	\$7,500.00			6	\$10,000	\$0
24	Water Treatment Plant	1		\$2,500.00	\$0.50	\$1,000.00	60	\$30	6	\$4,220	\$4,220
	Water Storage (gal)	25000	0	\$250,000.00		\$40,000.00			6	\$290,000	\$0
26	Sewage Treatment	1		\$10,000.00	\$0.25	\$7,500.00	35	\$9	6	\$17,710	\$1,000
	Sewage Disposal piping	200		\$25.00		\$35.00				\$12,000	\$0
28	Camp Shut-down	1		\$10,000.00						\$10,000	\$10,000
	Total									\$453,102	\$112,392

Assumes Genset and fuel system is owned by contractor and shipped to site

Assumes ATCO trailers owned by contractor- only cost is installation & operation: Mob/Demob covered under separate item Assumes water storage tank is permanent tank for village

TOTAL: \$902,670

Construction Camp Cost Estimate New Site Task Costs

Task/Item	Quantity	Capital Cost	Machine Cost/hr	Personnel Cost/hr	Hours/wk	Weekly Total	Months	Season Total	Season Total
Camp Cost/Day	Quantity	Capital Cost	Machine Cost/hr	Personnel Cost/hr	Hours/wk	Weekly Total	Months	Season Total	Season Total
				Installation Cost LS					
ATCO Trailers									
10 Camp Start-up	1	\$10,000						\$10,000	\$10,000
11 Sleeping	2	\$1,000						\$1,000	\$0
12 Shower/Clothes Washing/Dining	1	\$1,000						\$1,000	\$0
13 Office	1	\$1,000						\$1,000	\$0
14 Storage Conex	3	\$1,000						\$1,000	\$0
15 Food (per weekly meals)	504	\$5				\$2,520	6	\$60,480	\$60,480
16 Power Genset	1	\$0		\$5,000.00			6	\$5,000	\$1,000
17 Fuel Tankage	1	\$0		\$3,000.00			6	\$3,000	\$1,000
18 Operating Fuel (gals/hr)	8		\$3.00		168	\$4,032	6	\$24,192	\$24,192
19 Telephone	1	\$1,000		\$2,500.00			6	\$2,500	\$1,000
20 Develop Raw Water Source	1		\$2,500.00	\$7,500.00			6	\$10,000	\$0
21 Water Treatment Plant	1	\$2,500	\$0.50	\$1,000.00	60	\$30	6	\$4,220	\$4,220
22 Water Storage (gal)	5000	\$1,000		\$2,500.00			6	\$3,500	\$0
23 Sewage Treatment	1	\$10,000	\$0.04	\$7,500.00	35	\$1	6	\$17,534	\$1,000
24 Camp Security Fencing	1100	\$20,000							\$0
26 Camp Shut-down	1	\$10,000						\$10,000	\$10,000
Total								\$154,426	\$112,892

Assumes Genset and fuel system is owned by contractor and shipped to site
Assumes ATCO trailers owned by contractor- only cost is installation & operation: Mob/Demob covered under separate item

TOTAL: \$605,994

Power and Fuel Cost Summary

	Task/Item	Simiq	Tatchim Isua	lmnakuk	Kivalina	Kiniktuuraq	Igrugaivik	Kuugruak	Notes
1	Electical Distribution	\$1,236,500	\$1,236,500	\$1,236,500	\$1,236,500	\$1,236,500	\$1,236,500	\$1,236,500	(1)
2	Communications	\$640,000	\$640,000	\$640,000	\$640,000	\$640,000	\$640,000	\$640,000	(2)
3	AVEC Generation	\$2,165,000	\$2,165,000	\$2,165,000	\$2,165,000	\$2,165,000	\$2,165,000	\$2,165,000	(3)
4	Heat Recovery	\$250,000	\$250,000	\$250,000	\$250,000	\$250,000	\$250,000	\$250,000	(4)
5	Wind Generation	\$1,000,000	\$1,000,000	\$1,000,000	\$1,000,000	\$1,000,000	\$1,000,000	\$1,000,000	(5)
	Total Electrical Costs	\$5,291,500	\$5,291,500	\$5,291,500	\$5,291,500	\$5,291,500	\$5,291,500	\$5,291,500	(6)

Notes

- 1 Overhead electrical distribution system throughout village including: MV (15kV) conductors, poles, transformers, switches, cutouts and junction devices. Underground system cost similar.
- 2 Overhead telecommunications distribution system throughout village including: Copper telephone cabling, Cable TV cabling, fiber optic cabling and switches and routing devices. Underground system cost similar.
- 3 Including all modules, installation, generation equipment, site and pad work and utility connections.
- 4 Including module, all equipment, installation and interconnection.
- 5 Including turbines, installation and interconnection.
- 6 At this stage of design electrical costs for all sites similar. Minor adjustments are anticipated as the design progresses further.

KIVALINA BUILDINGS COST ANALYSIS FOR MOVING AND CONSTRUCTION OF NEW BUILDINGS

TNH BLDG #	DOWL BLDG#	BUILDLING NAME				Co	OSTS
			NO. OF UNITS	COST PER UNIT	SUBTOTAL	RELOCATION	REPLACEMENT
45	28	City Storage Building	N/A	N/A	N/A	\$226,850	\$336,000
48	29	IRA Office	N/A	N/A	N/A	\$717,850	\$862,400
52	33	Post Office	N/A	N/A	N/A	abandon	\$560,000
66	42	Episcopal Church	N/A	N/A	N/A	\$360,250	\$756,000
74	46	Boys & Girls Club	N/A	N/A	N/A	\$301,600	\$985,600
75	47	Community Center / Bingo Hall	N/A	N/A	N/A	abandon	\$918,400
77	50	National Guard Armory	N/A	N/A	N/A	\$282,850	\$1,280,000
79	52	Old Clinic	N/A	N/A	N/A	\$249,650	\$280,000
80	53	New Clinic	N/A	N/A	N/A	\$226,850	\$608,000
94	-	Friends Church	N/A	N/A	N/A	abandon	\$588,000
120	89	School Shop	N/A	N/A	N/A	\$244,100	\$446,400
122	80	Native Store / Warehousing	N/A	N/A	N/A	abandon	\$720,000
123	81	Native Store Storage	N/A	N/A	N/A	abandon	\$218,400
128	82	Kivalina Native Store	N/A	N/A	N/A	\$816,800	\$937,200
131	93	Teacher Storage	N/A	N/A	N/A	abandon	\$216,000
143	-	School Relocatable	N/A	N/A	N/A	\$69,550	\$0
144	60	Washeteria / Water Treatment Plant	N/A	N/A	N/A	abandon	N/A
xx	xx	Residential Homes (71 each)	71	\$300,000	\$21,300,000	abandon	\$21,300,000
107	XX	School	N/A	N/A	N/A	abandon	\$25,000,000

shaded cell is used for cost estimates

TOTAL RELOCATION COSTS (MOVE BUILDINGS) = \$1,124,950 TOTAL REPLACEMENT COSTS (NEW BUILDINGS) = \$52,692,400

Building 45 – City Storage

Year of Construction: unknown

Type of Construction: Foundation – 4x12 Timber Sleeper

Floor – Lumber joists on top of foundation Walls – Wood stud with T1-11 siding Roof – 3:12 Truss with metal roofing Mechanical/Heating – unknown

Electrical – unknown

Building Size: $28 \times 40 = 1,120 \text{ sq. ft.}$

Condition: This building appears to have gone through an evolution of uses with decreasing levels of maintenance. The siding does not extend over and past the floor framing or the wall sill plates. The floor system is covered with a 2x lumber trim board which also acts as a rim joist. Given that the floor framing and wall sill plates are not protected from the weather, it is suspected that significant rot is present in the structural framing.

Recommendations: Although the building does appear to be relocatable as a single unit, it probably is not worth relocating. Particularly given the high probability of rot in the floor system and the building's diminishing value to the community.

Cost:	Relocation	Building Preparation	40 crew hours @ 575	\$ 23,000
		Transport	10 crew hours @ 575	\$ 5,750
		New Foundation	24 crew hours @ 575	\$ 13,800
		Installation	100 crew hours @ 575	\$ 57,500
		Replace Electrical	_	\$ 37,500
		Replace Plumbing/Heati	ng	\$ 60,000
		ADA Compliance	-	\$ 14,300
		Materials		<u>\$ 15,000</u>
		Total Relocation Costs		\$ 226,850
	Replacement	(Pre-Engineered Metal E	Bldg) 1120 sq. ft. x \$300	\$ 336,000

Building 48 - IRA Office

Year of Construction: unknown

Type of Construction: Foundation – Timber Beam on Buried Timber Piers

Floor System – 1st Floor, Exposed Lumber joists

Floor System – 2nd Floor, unknown

Wall – Conventional Timber Framing with Plywood sheathing on 1st Floor

and T1-11 Sheathing on 2nd Floor Roof – 4:12 Truss with metal roofing

Mechanical/Heating – Oil Fired Forced Air Furnace with secondary room heaters.

Building Size: 28x44; 1232 sq. ft. / floor x 2 = 2464 sq. ft.

Condition: This building started out as a single story building. The building was at some point raised and a new first floor was in-filled. This in-fill appears to have been constructed without the benefit of engineering or under the guidance of a skilled construction superintendent. The building photos revealed that the floor framing and the grade beam are in violation of the building code for moisture proofing and loading. The wall openings for doors and windows have no structural headers. The interior stairway violates the code requirement for rise, run and landings.

The forced air heating system appears to be a residential unit that is seriously undersized for this building, particularly in the ductwork.

Given the extensive use of electrical extension cords, it appears that the building's electrical system is also undersized for this facility. The photos do reveal a code violation at the breaker panel with the exposed surfaced mounted romex.

Recommendations: It appears that the original portion of the building could be relocated. However, the in-filled first floor would require an extensive amount of shoring and bracing in order to make it strong enough to survive relocating the building intact. Then once in place, the in-filled first floor would require structural retrofitting to bring it minimally into code compliance. Relocation of this building is not recommended.

Cost:	Relocation		
	Building Preparation	40 crew hrs @ 575	\$ 23,000
	Second Floor temporary falsework	60 crew hrs @ 575	\$ 34,500
	First Floor demolition	60 crew hrs @ 575	\$ 34,500
	Second Floor Lowering & Trailoring	24 crew hrs @ 575	\$ 13,800
	Transport	10 crew hrs @ 575	\$ 5,750
	Second Floor Jackup & Falsework	60 crew hrs @ 575	\$ 34,500
	New Foundation (Post on Pad)	24 crew hrs @ 575	\$ 13,800
	New First Floor & Stairway	1232 sq ft @ 350	\$ 431,200
	Replace heating system and plumbing		\$ 60,000
	Replace electrical		\$ 37,500
	ADA Compliance		\$ 14,300
	Materials		\$ 15,000
	Total Relocation Costs		\$ 717,850

Replacement

2464 sq. ft x \$350 \$862,400

Building 52 – U.S. Post Office

Year of Construction: estimated 1979 - 1980

Type of Construction: Modular wood framed building on an unknown foundation type

Heating: preway oil burner, appears inactive; 2 monitor type room heaters

Building Size: 10x54 = 540 sq. ft.

Condition: This building was originally developed in the early 1980s by USPS as a short-term solution to the postal needs of Alaska's remote communities. The minimum facility specifications of the USPS has undergone significant revisions during the last twenty years. The biggest impact on this facility are the more recently adopted security measure and accessibility standards.

Recommendations: Although this building can be relocated with minimal preparation or retrofitting, it does not meet the minimum standards for a Postal Facility. Therefore, replacement is the more cost effective solution.

Cost: Relocation N/A

Replacement (USPS Min) 1100 sq. ft. x \$500 = \$560,000

Building 66 – Episcopal Church

Year of Construction: unknown, with recent addition

Type of Construction: Foundation: Timber beam on timber crib

Floor: lumber floor joists

Walls: conventional framing with plywood sheathing

Addition has T1-8 sheathing Roof: 4:12 Scissor Truss with metal roofing Heating: 2 monitor style room heaters

Building Size: 30x72 = 2160 sq. ft. single-story

Condition: The building appears to be well maintained and deterioration of its structural systems were not noted in the photographs. The electrical system appears to be outdated, particularly the breaker panel has not been produced for several decades.

Recommendations: Simply through the passage of time, the electrical system no longer meets code and will have to be replaced. The floor system appears to be overstressed given the wide spacing of the floor joists in the addition. Additional joists will need to be added to bring the floor loading capacity into the code minimum. The building does appear to be relocatable but it will have to be cut into sections width-wise in 24-foot section. These sections will then need to be temporarily reinforced.

Cost: Relocation

Building Preparation	40 crew hrs @ 575	\$ 23,000
Separate Modules (3 modules @ 20)	60 crew hrs @ 575	\$ 34,500
Transport (3 modules @ 10)	30 crew hrs @ 575	\$ 17,250
New Foundation (Post on Pad with Glu-Lam)	24 crew hrs @ 575	\$ 13,800
Remarry Modules (3 modules @ 40)	120 crew hrs @ 575	\$ 69,000
Building Installation	100 crew hrs @ 575	\$ 57,500
Floor Stiffening	32 crew hrs @ 575	\$ 18,400
Replacement of Electrical System		\$ 60,000
Install new Plumbing and Heating		\$ 37,500
ADA Compliance		\$ 14,300
Materials		\$ 15,000

Total Relocation Costs \$ 360,250

Replacement: 2160 sq. ft. x \$350 \$756,000

Building 74 – Boys & Girls Club

Year of Construction: unknown

Type of Construction: Foundation: Post on Pad

Floor: Joists (lumber or BCI?) on top of Glu-Lam

Walls: conventional framing, deep wall (2x8?) with T1-11 sheathing

Roof: 4:12 Truss with metal roofing Heating: monitor style space heaters

Building Size: 44x64 = 2816 sq. ft. single-story

Condition: The building appears to be structurally sound. Depending on the type of roof used, it is possible to relocate this building by splitting it in half lengthwise. The electrical breaker panel is in serious disrepair and does present an eminent life-safety condition. It needs to be repaired immediately.

Recommendations: This building is a good candidate for relocation. However, given its width, it will probably need to be split in half lengthwise with temporary structural reinforcing along the marriage line of each half. Assuming full-length trusses, an engineering gusset or load-bearing beam will be required to remarry the sections.

Cost: Relocation

Building Preparation	40 crew hrs @ 575	\$ 23,000
Separate Modules	40 crew hrs @ 575	\$ 23,000
Transport (2 modules @ 10)	20 crew hrs @ 575	\$ 11,500
New Foundation (Post on Pad)	24 crew hrs @ 575	\$ 13,800
Remarry Modules	80 crew hrs @ 575	\$ 46,000
Building Installation	100 crew hrs @ 575	\$ 57,500
Install Plumbing and Heating		\$ 60,000
Update and repair Electrical		\$ 37,500
ADA Compliance		\$ 14,300
Materials		\$ 15,000

Total Relocation Costs \$301,600

Replacement: 2816 sq. ft. x \$350 \$985,600

Building 75 – Community Center / Bingo Hall

Year of Construction: photo indicates construction during the late 1950s / early 1960s

Type of Construction: Foundation: Timber Post on Wood Sleeper

Floor: assumed lumber joists

Walls: conventional framing with plywood sheathing

Roof: assumed on-site built knee-brace truss with metal roofing

Heating: very old oil-fire furnace force air room heat; i-monitor style room heater

Electrical: surface mounted in conduit

Building Size: 41x64 = 2624 sq. ft.

Condition: The original building appears to have been 30x64 with a small arctic entry. The building was then enlarged with a 12-foot wide full length addition and the arctic entry was made wider. The roof of the addition was installed by simple spanning to the then existing roof plane and sheathed over.

The building has suffered from a lack of effective maintenance and is exhibiting conditions of advanced rot in the sheathing. Additionally, all ventilation to the roof system has been closed off making it highly likely that rot is occurring in the roof system.

Recommendations: Replacement only

Cost: Relocation N/A

Replacement: 2624 sq. ft. x \$350 = \$918,400

Building 77 - Armory

Year of Construction: original building – late 1960s / early 1970s

Addition - mid 1980s

Type of Construction: Foundation – Original: modified post on pad

Foundation – Addition: post on pad Floor: original bldg assumed lumber joist

Walls: original bldg assumed conventional framing

Roof - Original: unknown

Roof – Addition: appears to be either pre-manufactured module or panelized

Heating: unknown Electrical: unknown

Building Size: Original: 20x60 = 1200 sq. ft.

Addition: 30x40 with 10x16 hall connection = 1360 sq. ft.

Total Building Size 2560 sq. ft.

Condition: The addition is fairly recent and appears to be sound. This building can be relocated but the method of relocation depends on whether it is a modular or panelized building.

The original building also appears to be structurally sound. However, at some point in time, urethane foam was applied to the underside of the building. Urethane foam locks moisture into the surfaces that it is applied to and accelerated rot is introduced within the first year or two after application. This warrants detailed investigation and testing.

Recommendations: Assuming that no rot is present in the floor system of the original building, the facility is a good candidate for relocation.

^ ·	
Cost:	Relocation
OUSI.	Relocation

VII		
Building Preparation	40 crew hrs @ 575	\$ 23,000
Transport	10 crew hrs @ 575	\$ 5,750
New Foundation	24 crew hrs @ 575	\$ 13,800
Building Installation	100 crew hrs @ 575	\$ 57,500
Reconstruction of Hallway	160 sq ft @ 350	\$ 56,000
Heating/Plumbing Update		\$ 60,000
Electrical System Update		\$ 37,500
ADA Compliance		\$ 14,300
Materials		\$ 15,000

Total Relocation Costs \$ 282,850

Replacement: 2560 sq. ft. x \$500 \$1,280,000

Building 79 – Old Clinic

Year of Construction: late 1970s / early 1980s

Type of Construction: Foundation: Double 2x sistered beam on buried log pier

Floor: Assumed lumber joist with plywood soffit Walls: conventional framing with plywood sheathing

Roof: 4:12 Truss with metal roofing Heating: monitor style room heaters Electrical: surface mounted in conduit

Building Size: 20x40 = 800 sq. ft.

Condition: This building appears to be structurally sound. However, the structural sheathing indicates significant amounts of delamination. Mold growth is noted to be occurring on the shade side of the building. Therefore, the remaining strength of the sheathing is questionable. The interior hallway width does not appear to meet code.

Recommendations: With the replacement of the exterior sheathing, this building is a good candidate for relocation.

Cost: Relocation

Building Preparation	40 crew hrs @ 575	\$ 32,000
Sheathing Replacement	24 crew hrs @ 575	\$ 13,800
Transport	10 crew hrs @ 575	\$ 5,750
New Foundation (Post on Pad)	24 crew hrs @ 575	\$ 13,800
Building Installation	100 crew hrs @ 575	\$ 57,500
Install Plumbing and Heating		\$ 60,000
Install Electrical		\$ 37,500
ADA Compliance		\$ 14,300
Materials		\$ 15,000

Total Relocation Costs \$ 249,650

Replacement: 800 sq. ft. x \$350 \$280,000

Building 80 - New Clinic

Year of Construction: mid 1980s

Type of Construction: Foundation: wood framed plywood shear perimeter wall and beam on timber

pier midwall

Floor: TJI with plywood soffit on bottom flange

Walls: conventional framing with plywood sheathing. A combination of T1-11

and shiplap siding is applied over the sheathing.

Roof: 4:12 Truss with metal roofing Heating: oil fired forced air furnace

Building Size: 32x38 = 1216 sq. ft.

Condition: This building appears to be structurally sound. However, it does suffer from a lack of effective maintenance. The photo of the secondary egress door is curious and may simply be distortion in the photo. However, if it is not, the door distortion combined with the bowing of the ceiling tile track are an indication of structural failure in the building wall. This needs to be clarified.

The sanitary waste line in the crawl space indicated that this building has a long history of failure and patch job repairs. The waste lines must be fully replaced.

The forced air heating system is also suffering from a lack of servicing and several minor code violations are apparent in the photos.

The electrical system appears to be seriously undersized and overstressed. This is evidenced by the numerous post-it notes on the breaker panel and the spaghetti web of extension cords. This building is a high risk of electrically-generated fire.

Recommendations: Although this building is relocatable, it is seriously undersized and underequipped to meet the current federal and state health care standards. Therefore, its relocation is not recommended unless it is for an alternate function.

Relocation	Building Preparation	40 crew hrs @ 575	\$ 23,000
	Transport	10 crew hrs @ 575	\$ 5,750
	New Foundation	24 crew hrs @ 575	\$ 13,800
	Building Installation	100 crew hrs @ 575	\$ 57,500
	Install Plumbing/Heating		\$ 60,000
	Install Electrical		\$ 37,500
	ADA Compliance		\$ 14,300
	Materials ·		\$ 15,000
	Total Relocation	Costs	\$ 226,850
	Relocation	Transport New Foundation Building Installation Install Plumbing/Heating Install Electrical ADA Compliance Materials	Transport 10 crew hrs @ 575 New Foundation 24 crew hrs @ 575 Building Installation 100 crew hrs @ 575 Install Plumbing/Heating Install Electrical ADA Compliance

Replacement: 1216 sq. ft. x \$500 \$608,000

Building 94 - Friends Church

Year of Construction: Original – unknown

Addition - unknown

Type of Construction: Foundation: grade beam on sleepers

Floor: lumber joists

Walls: conventional framing with T1-8 sheathing

Roof - Original: simple span joists with offset at ridge beam, asphalt singles and

on-roof ventilators.

Roof – Addition: 4:12 Truss with metal roofing

Heating: monitor style room heater

Building Size: Original: 24x42 = 1008 sq. ft.

Addition: 24x28 = 672 sq. ft. Total Size = 1,680 sq. ft.

Condition: This building appears to be structurally sound and has had a good level of maintenance. However, the asphalt roofing on the original building is in dire need of replacement evidenced by the deterioration of the roofing shingles. It is highly likely that water and moisture has entered the roof system and that rot is present throughout.

The building appears to be in violation of the building code for minimum Light and Vent and for Exiting. However, these can be easily corrected.

The photos indicate that there is only one room heater for the entire building. Since this is a place of assembly, the mechanical code does require a much higher level of heating and ventilation.

Recommendations: This facility does appear to be relocatable. However, the condition of the roof system of the original building needs to be evaluated prior to making the determination.

Given that the building is founded on grade beams, the preparation of the building for moving will require excavation (by hand) around and under the building for insertion of support beams.

Additionally, this building will need to be separated at the marriage line of the original building and the addition.

Once moved, the building will require installation of additional windows, at least one more fire exit and a complete heating/ventilation system.

The relocation of this building will be a time and labor consumptive process just to get it prepared for relocation. Additionally, during the excavation process, the building will be at risk for failure if it becomes overstressed. Therefore, its relocation is not recommended.

Cost: Relocation N/A

Replacement: 1680 sg. ft. x \$350 = \$588,000

Building 107 McQueen School

Year of Construction: early to mid 1980s

Type of Construction: Foundation – Pile, appears to be steel

Floor – web truss assumed

Walls – pre-engineered metal frame and/or Glu-lam, assumed

Roof – varies, 2:12 truss at gym, flat roof elsewhere

Building Size: see attached sketch – 20,000 sq. ft.

Condition: The photographs are insufficient to make an assessment. The aerial

photograph, see attached, indicates that the building structural elements are broken into four interdependent

cells.

Recommendations: This is a fairly large building that does not lend itself well to relocation. The building appears that it can be separated into four modules using a fully engineered system to separate and reinforce each module. This will then result in four large modules that will require custom trailoring to transport. However, until more information is known, relocation of this complex building is not recommended.

Cost: Relocation N/A, insufficient information available.

Replacement 20000 sq. ft. x \$500 = \$10,000,000

Building 120 School Shop

Year of Construction: unknown

Type of Construction: Foundation (Original & 1st Add'n) – Timber beam on Log Pier

Foundation (Generator Add'n) – unknown Floor (Original) – TJI on top on lumber beams

Floor (1st Add'n) – Lumber joists inset between floor beam

Floor (Generator Add'n) - Floor on grade

Walls – Conventional framing with T1-8 Sheathing on original and generator

addition; plywood on 1st Addition.

Roof (Original) – 3:12 Truss with metal roofing

Roof (1st Add'n) - Lumber joist shed roof with metal roofing

Roof (Generator Add'n) – Simple span lumber joist Mechanical/Heating – 2 monitor-style room heaters

Electrical – unknown

Building Size: (Original) $24 \times 40 = 960 \text{ sq. ft.}$

(1st Add'n) 24x12 = 288 sq. ft.

(Generator Add'n) 20x12 = 240 sq. ft.

Total Building Size = 1488 sq. ft.

Condition: The original building and the 1st Addition appear to be structurally sound and are good candidates for relocation. The generator addition does not appear to be structurally strong enough to survive relocation. The standby generator is installed on top of timber sleepers with no lateral supports and is at risk of overturning when in operation.

Recommendations: The generator addition is structurally deficient and will not survive relocatation. The original building and 1st Addition can be relocated as separated whole-width modules. The electrical system will need to be update to bring it into code compliance.

Cost:	Relocation	Building Preparation Module Separation Generator Room Demo Transport New Foundation Installation Electrical Update Plumbing/Heating ADA Compliance Materials Total Relocation	40 crew hours @ 575 20 crew hours @ 575 10 crew hours @ 575 10 crew hours @ 575 24 crew hours @ 575 100 crew hours @ 575	\$ 23,000 \$ 11,500 \$ 5,750 \$ 5,750 \$ 13,800 \$ 57,500 \$ 37,500 \$ 60,000 \$ 14,300 \$ 15,000 \$ 244,100
	Replacement	(Pre-Engineered Metal Bl	dg) 1488 sq. ft. x \$300	\$ 446,400

Building 122 - Native Store / Warehousing

Year of Construction: The original building appears to be consistent with construction methods of pre-

1960 and there has been 5 additions made since then.

Type of Construction: This facility is all wood frame construction with each addition utilizing different

techniques.

Building Size: 2,400 sq. ft.

Condition: This seems to be a very complicated structure. It appears that the original building is the only structurally independent element of the complex.

Recommendations: Given the structural interdependence of each addition to each other, relocation of this facility is not a viable option. Therefore, it should be replaced.

Cost: Relocation N/A

Replacement: (Pre-engineered metal building) 2400sq. ft. x \$300 \$720,000

Building 123 – Native Store Warehouse

Recommendations: This building is a threat to life safety and needs to be condemned. Replace with pre-engineered metal building.

Cost: Relocation N/A

Replacement: Pre-Engineered Metal Bldg (26x28) 728 sq. ft. x \$300 = \$218,400

Building 128 - Native Store

Year of Construction: early 1990s

Type of Construction: Foundation: unknown, the foundation is fully skirted

Floor: unknown, probably TJI on Glu-Lam

Walls: appears to be a pre-engineered metal building

Roof: see Walls

Heating: oil fired forced air furnace

Electrical: unknown

Building Size: 42x60 with buildouts 1) 8x10, 2) 18x10, 3) 10x8 and 4) 22x12 = 3124 sq. ft.

Condition: The photography provided is not sufficient to make an informed determination. However, the electrical system at the breaker panel has been modified with numerous code violations evident in the photo.

Recommendations: Relocation of this building will require that it be disassembled into panelized sections and reassembled at the new site.

Cost:	Relocation	Disassembly	400 crew hours @ 575	\$ 230,000

 Reassembly
 800 crew hours @ 575
 \$ 460,000

 Replace Mechanical
 \$ 60,000

 Replace Electrical
 \$ 37,500

 ADA Compliance
 \$ 14,300

 Materials
 \$ 15,000

Total Relocation Costs \$816,800

Replacement: Pre-Engineered Metal Bldg 3124 sq. ft. x \$300 \$937,200

Building 131 Teacher Storage

Recommendations: This building is in a serious state of deterioration and will not survive relocation. Therefore it should be replaced.

Cost: Relocation N/A

Replacement: Pre-engineered Metal Building (18x40) = 720 sq. ft x \$300 = \$216,000

Building 143 School – Relocatable Classroom

Recommendations: This is a recently installed modular building that is designed to be relocated and still has its trucks installed. Therefore, the costs to be relocated and make operational will be minimal.

Cost:	Relocation	Building Preparation Transport Foundation (use existing) Installation Electrical Update (n/a) Mechanical Update (n/a) ADA Compliance Materials	10 crew hours @ 575	\$ 23,000 \$ 5,750 \$ 5,750 \$ 5,750 0 0 \$ 14,300 \$ 15,000
		Total Relocation	Costs	\$ 69,550

Replacement: N/A

Building 144 Washeteria / Water Treatment Plant

Year of Construction: early 1980s

Type of Construction: Foundation – Timber beam on Post with buried pad

Floor – TJI floor joist on top of beam

Walls - Conventional framing with T1-11 Sheathing

Roof – 4:12 Truss with metal roofing

Building Size: Two sections of 18x28 = 1008 sq. ft.

Condition: This is a well-maintained facility that is structurally sound. No obvious code

deficiencies were noted in the photos.

Recommendations: Although this building is a good candidate for relocation from a structural standpoint, it is not practical to do so because of the highly sophisticated and complex mechanical/electrical systems. Given that the new community site is intended to have a fully piped water supply and sewer systems, this facility's systems simply cannot be retrofitted for the new community.

Cost: Relocation N/A

Replacement 2400 sq. ft. (minimum) x \$500 = \$1,200,000



Kivalina Gravel Cost/Time Analysis

OBJECTIVE! DETERMINE TIMELINE AND COST TO CONSTRUCT
GRAVELISITE PAD.

- ASSUME! 1). OBTAIN FILL/GRAVEL FROM KISIMIGIUM HILL WITH BLASTING TECHNIQUES.
 - 2). PERMITS ARE PART OF EA/ETS PROCESS
 - S) BARGE EQUIDMENT IN DURING SUMMER. USE ICE ROADS TO MOVE EQUIDMENT TO KISIMIGAK HILL
 - 4). HAUL DISTANCE ECLAL BETWEEN 21/2 mil-s to 7 MILES, DEPENDING ON THE SITE. DISTANCE IS ONE-WAY.
 - 5). HAUL RUHD Steet deep by 30 FEET WIDE.

SOLUTION!

Quantity Fee Road / Site Pad = 1,536,193 xd3 who et read 1,844,193 yd3 who road

Time to Ital Analysis

Assume 11) winter natice to proceed

- 2) Louse equipment for barge delivery in summer
- 3) Store equipment and camp symplers in Kivalina until Tanvary, holding to giace ofte
- 1) Deal Blast from Jan through construction and.
- 5) Have Place Call Sum late April on continue throughout Project. Place over tendra of Tahric. Single snow away.

ES.	DATE	
н.	DATE	
В.	SHEET OF	-
DB NO.	SCALE	_



Engineering • Surveying • Landscape Architecture

Kivalina Gravel/Fill
Haul time/cestr

How Long to Haul?

From meeting with wilder Construction; wilder developed / Hauled and placed 1,00,000 yd 3 in a western Haska site last year. They perfermed the weste in 1-year. They can build a 1.5 to 1.8 million you pad in Z to 3 years.

From Anchorage / C street / UAP contractors - Developed / Havied / Placed 250,000 yd3 material in 8 weeks.

ANSWER: HAULING/PLACING DEAENDS ON EQUIPATENT.

Based placement by Quantity. Wilder states they can place = 20,000 yds per week, they can also place Is million yd3 in 1 to Z yrs.

Assume 8 trucks @ 25 yes each, I mile (max) enemay top 40 minutes / trip (Komatsu MT36 or equal acticlated truck)

> 8 + 25yds = 200 yds / 44 min = 300 yds /hr 12 hr days = 3,600 day 7 days / need = 25,200 need

75, 700 yd3/weeil # 48 weeks (Full Season (taul) = 1,709,600 / xr.

1.8 = 1.5 years. Require 1,8 million yds

Placement of full requires 1.5 x15, mobilization requires Sept -> April = 8 ments

Total time = 1.5 +8 = 2.3 years.

Say 2 to 3 years

DES.	DATE	
<u> </u>	DATE	
F.B.	SHEET Z	of 5



Tryck Nyman Hayes, Inc.

Engineering • Surveying • Landscape Architecture

Kivalina Gravel / Fill Haul time / cests

Costs:

Kinalina growl stedy had \$40 ton = \$60/xds

Kitable costs w/ had = \$30/yd3 (Signe Construction)

Majest Ketz crats

Regional / Remete Factor = 1.5 = \$15/yds Winter work Factor = 1.5 515/yds

Contingency = 20% -12/1d

572/yd 59x \$70/yd3

DES.	DATE
CI	DATE
F.B.	SHEET OF
JOB NO.	SCALE



Kivalina Quantity Calculations

2,880,000 short tons

Townsite will cover 100 acres at an average depth of 9 to 14 feet depending on gravel specifications, with 1V:3H sideslopes Assume townsite is a rectangle 1,500 ft by 2900 ft

Units

1 Acre = 43,560 sq ft.

1 meter = 3.2808 ft. 1 cu yd = 27 cu ft. 1 cu yd = 1.5 short tons 1 cu yd = .7646 cu, meters

Main Townsite pad

Reduced with Insulation (not recommended due top long term risks)

Access Road

4,356,000	sq ft
9.000	depth in

5.391 ft 39,204,000 cu ft 23,483,719 1,452,000 cu yds 1,110,199 cu meters 869.767 2,178,000 tons 1,304,651

Sideslopes

\$

8,800	ft perimeter			
	ft height			9.514
39.369	ft base			28.543
	sqft unit are	ea.		135.783
2,273,213				1,194,894
84,193		64,374	cu meters	44,255
126,290	tons	1,174,573	cu meters	66,383

25% Contingency

1,371,034 tons 342,759 25% contingency 1,713,793 tons total

2,880,362 tons total 2,880,000 rounded

2,304,290 tons

576,072

1,714,000 rounded

1,536,193 CUBIC YARDS without road 134,426,496.17 cost for gravel in place

1,844,193 CUBIC YARDS with access road

Reduce Pad Thickness with Insulation (not recommended for a community site pad)

sideslope

is with insulation (not recommended for a community site page)
5.1 meters MSL = minimum elevation for flooding
2.2 meters MSL = mean site elevation
2.9 meters = thickness of gravel required for flooding
4.0 meters = thickness of gravel required for thermal insulation
1.1 meters = thickness that could be reduced by use of insulation

3.6 feet = thickness that could be reduced by use of insulation

25 mm of insulation = 300 mm of gravel

3.608924

1.1 meters gravel = 3.6 inches of insulation

1,166,000.000 tons reduction

7 Miles 30 width 5 Depth 3 to 1

8,316,000 cu ft 308000 cu yds 462000 tons

46.670 \$/ton (TNH adjustedcorps # of \$40/ton)

\$54,417,220.00 Savings from gravel reduction

\$1.60 Cost of insulation sq ft/in


4,356,000 sq ft

3.6 in insulation

\$25,090,560.00 Cost of insulation

\$29,326,660 savings based on cost difference between gravel and insulation (does not include cost of delivery to site and placemen)

cubic ft cubic vds tons 4,356,000 13 125 57,172,500 2,117,500 3,176,250 cuyd 2,100,000 2,800,000 m3 4200000



SCALE! 11 = 2 miles